


# FIELD INSPECTION REPORT

|                                                                               |  |                    |
|-------------------------------------------------------------------------------|--|--------------------|
| Date of Inspection : 9/12/20                                                  |  | District: Araria   |
| Division : forbesganj                                                         |  | Length (km): 4.710 |
| Name of the Road: Araria - Paniganj Road Kunjrali Tola to Paniganj forbesganj |  |                    |
| Scheme/Programme: MAINTENANCE                                                 |  |                    |
| Package No.:                                                                  |  | Road Id No.:       |
| Status of the Project: Ongoing/Completed/Under Maintenance                    |  |                    |
| Work is a case of: New Connectivity/Up gradation/ Maintenance                 |  |                    |

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | <b>Pavement</b>                                                                                                      |           |
| a)      | Road Junction condition                                                                                              | ✓ S/U     |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U     |
| c)      | Riding Quality                                                                                                       | ✓ S/U     |
| d)      | Road Camber                                                                                                          | ✓ S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No  |
| 2.      | <b>Cross Drainage</b>                                                                                                |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U   |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓ S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U   |
| 3.      | <b>Road Furniture</b>                                                                                                |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No  |
| 4.      | <b>Compliance History</b>                                                                                            |           |
| a)      | Status of ATR's & any others                                                                                         |           |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

  
 (Signature)

NAME: