

FIELD INSPECTION REPORT

Date of Inspection : 04/12/2020		District: EAST CHAMPARAN
Division : MOTIHARI		Length (km): 3.078 km
Name of the Road: NH-28A TO JHAKHIYA NYKA TOLA		
Scheme/Programme: MAINTENANCE		NABARD
Package No.: -		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

FINDING:- 300 m Road Surface damaged due to flood 2019-20 and 2020-21. Rest surface Satisfactory.

(Signature) AE

NAME: AKHILESH PRASAD

DESIGNATION: A-E, WORKS SUB-DIVISION, BANJARAYA
(MOTIHARI DIVISION)

NAME: - ABHIMANYU TANTI
DESIGNATION: - J-E, BANJARAYA/KOTWA

Aug
07/12/2020
J-E