The same of the sa	FIELD INSPECTION REPORT	
Date of	Inspection: Louis	
Division	a: Rio - Huralator	
Name o	f the Road: Surendra paswan ke shay se banjana ster tot Programme: MAINTENANCE	
Scheme	The Charles and an interest	
Package	No.	SECTION VALUE STATES
Status o	the Project: Ongoing/Completed/Under Maintenance	312
The same of the same of	a case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	
1.	Pavement	Remarks
a)	Road Junction condition	
b)		SAS
	Condition of Surfacing	3/1/
(c)	Riding Quality	S/Jd
d)	Road Camber	S/V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
1)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	Y,es/No
(a)	The state of the s	
	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
	Condition of Absorbert & Wing walls, Slab in RCC culverts	S/SRI/U
	Control of all ages to be grown for Strings	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	VAS/No
THE RESERVE THE PARTY OF THE PA	Compliance History	*
4	MANAGEM MANAGEM AND	110
THE OWNER OF THE PARTY OF THE P		40
THE OWNER OF THE PARTY OF THE P	Status of ATR's & any others	11
THE OWNER OF THE PARTY OF THE P	ating :	
(a)	ating : Satisfactory (S)	Ŝ
(a)	ating :	