


FIELD INSPECTION REPORT

| | | |
|--|--|-----------------------------|
| Date of Inspection : 16.12.20 | | District: Madhubani |
| Division : Jainagar | | Length (km): 0.76 km |
| Name of the Road: PND Path to Jathi Mahabodhi | | |
| Scheme/Programme: MAINTENANCE | | |
| Package No.: | | Road Id No.: |
| Status of the Project: Ongoing/Completed/Under Maintenance ✓ | | |
| Work is a case of: New Connectivity/Up gradation/ Maintenance ✓ | | |

| Sl. No. | Parameters to be checked | Remarks |
|-----------|--|-------------------|
| 1. | Pavement | |
| a) | Road Junction condition | ✓ S/U |
| b) | Condition of Surfacing | ✓ S/U |
| c) | Riding Quality | ✓ S/U |
| d) | Road Camber | ✓ S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓ Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | ✓ Yes/No |
| g) | Compaction of flank/slope & raincuts if any | ✓ Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | ✓ S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | SRI No |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U) | |


16/12/20
(Signature)

NAME: Dilip Kumar

DESIGNATION: JE