

FIELD INSPECTION REPORT

Date of Inspection :	District: <i>East Champaran</i>
Division : <i>Arc 807</i>	Length (km): <i>2.411</i>
Name of the Road: <i>Nawada badhaca tola to noniya tola.</i>	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.: <i>31708300310</i>
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<i>Yes</i> Yes/No
f)	Contraction Joints provided or not (CC Pavement)	<i>Yes</i> Yes/No
g)	Compaction of flank/slope & raincuts if any	<i>N/A</i> Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<i>N/A</i> S/SRI/U
c)	Condition of railings/slab/approach for Bridges	<i>N/A</i> S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>Yes</i> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: *Mahendra Kumar*

DESIGNATION: *A.E.*

R.W.D. Dorega