## FIELD INSPECTION REPORT

		10/12/20	District: East Champara	·~
			Length (km): 1.00	
Name of the Road: Toy to Islamfur				
Scheme/Programme: MAINTENANCE MMGSY (SC)				
Package No.:		Road Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.	and the second section of	Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			<b>%/U</b> ′,
c)	Riding Quality			√S/U
d)	Road Camber			~5/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			¥es/No
2.	Cross Drainag			and the state of t
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			\S/SRI/U
c)	Condition of railings/slab/approach for Bridges			8∕ŚRI/U
3.	Road Furnitui	<b>C</b>		Carlotte Control
a)	Whether sign stones/Pavemen	¥es/No		

Overall Rating

a)

Satisfactory (S)	(5);
Satisfactory but requires Improvement (SRI)	+
Unsatisfactory (U)	_

(Signature)

- MIA

NAME:

malehwan Sharma

Status of ATR's & any others

DESIGNATION:

J.E.