FIELD INSPECTION REPORT

Date o	f Inspection:	विभिन्न	District: Galt Chumana	W
Divisio	n: motific	hè	Length (km): 1.320	NAME OF TAXABLE PARTY.
		Toy-to KATA		
	e/Programme:	MAINTENANO	Road Id No.: -	
Packag	e No.:	O-going/Compl	leted/Under Maintenance	
Status of the 110jett				
11. 12. 14	the state of the s		Remarks	
Sl. No.	Parameters to doctoraco			
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			\\$/U
<u> </u>	Riding Quality			.\$/Ú
c)				\S/U
d)	Road Camber Whether free from defects such as visible cracks, exposed			Yes/No
e)	Whether free from defects such as visible ended, aggregates in case of CC Pavement.			4-65/110
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
				Yes/No
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Drainage S/SRI/U			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			\S/SRI/U
	Condition of railings/slab/approach for Bridges			vs/sri/U
c)	Road Furniture			
3.	Road Furnitur	Mary Late State of	D 10 8 200m	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			-N14

Overall Rating

(0)	(5)
Satisfactory (S)	_
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	

(Signature)

NAME:

maleshwar sharma

DESIGNATION:

J.E.