FIELD INSPECTION REPORT

Date Of Inspection	16.12.2020	District	Bhojpur
Division – PIRO, Block – PIRO		Length (km):	1.70 km
Name of the Road:	Agiaon Bazar to Zobaradih		
Scheme/Programme	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project :	Ongoing/Completeted/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓		

Sl No.	Parameters to be checked	Remarks
1	**Pavment**	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2	**Cross Drainage**	
a)	Condition of head walls in Hume pipe culverts including its painting	S/✓SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/✓SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	**Road Furniture**	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	**Compliance History**	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	" SRI"
Unsatisfactory (U)	

Name: Sushil Kumar

Designation Junior Engineer

16/12/2020

(Signature)