

FIELD INSPECTION REPORT

Date of Inspection : 14.12.20	District: Mayapuri
Division: P.W.D. Mayapuri	Length (km): 1.262
Name of the Road: Chauraha Bishunpur part 22	Scheme/Programme: MAINTENANCE
Package No.:	Road Id No.: 3100401330
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Satya Narayan Prasad

14.12.20
(Signature) J.E.

DESIGNATION: J.E.