

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020		District : East Champaran
Division : Chakia		Length (Km): 1.021 km.
Name of the Road : PMGSY Path Railway gunti kura to anusudait jati tola -		
Scheme/Programme :		MAINTENANCE MMGSY
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	-
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	S
c)	Condition of railings/slab/approach for Bridges	SRI
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	S
4,	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

NAME :

DESIGNATION :

Abhi
17/12/2020
JE

(Signature)