FIELD INSPECTION REPORT Date of Inspection: 16.12.2020 E. Champarn District: Division: Chakea Length (Km): 1.43 Name of the Road: Shir Sharan Rai Balva ke Balhan To Rameshue as padau MAINTENANCE Package No.: Road ID No .: Status of the Project : Ongoing/Completed/Under Maintenance Work is a case of ; New Connectivity/Up Gradation/ Maintenance Si. No. Parameters to be checked Remarks 1, Pavement a) Road Junction condition 15/ 5) Condition of Surfacing 101 c) Riding Quality 19/ d) Road Camber 151 Whether free from defects such as visible cracks, exposed aggregates in e) 101 case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) 151 g) Compaction of flank/slope & raincuts if any 10) 2. Cross Drainage a) Condition of head walls in Hume pipe culverts including its painting 101 b) Condition of Abutment & Wing walls, Slab in RCC Culverts 151 c) Condition of railings/slab/approach for Bridges 3, Road Furniture Whether sign board/informatory/cautionary Board/Km & 200m a) Stones/Pavement road markings are provided and maintained 4, Compliance History a) Status of ATR's & any others **Overall Rating** Satisfactory (S) Satisfactory but requires improvement (SRI) SRI Unsatisfactory (U) Epcc favenent damage by Nead.

S

P.

31

1 g 2 a) b) c) 3, a) 4, a)

NAME :

**DESIGNATION:** 

Scanned with CamScanner

(Signature)