

FIELD INSPECTION REPORT

Date of Inspection : 12/12/2020 District : East Champaran
 Division : Chalcia Length (Km): 1.257
 Name of the Road : Bakhar Pansahi Bypass to Rajin Bakhar

Scheme/Programme : MAINTENANCE

Package No.: Road ID No.:

Status of the Project : Ongoing/Completed/Under Maintenance

Work is a case of : New Connectivity/Up Gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	LS
b)	Condition of Surfacing	LS
c)	Riding Quality	LS
d)	Road Camber	LS
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No/Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	-
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3.	Road Furniture	
a)	Whether sign board/Informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :	Satisfactory (S)	LS
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

Handwritten signature and date
 14/12/2020
 A.E

NAME :

DESIGNATION :

(Signature)