

FIELD INSPECTION REPORT

Date of Inspection : 12/12/2020	District : East Champaran
Division : Chapria	Length (Km): 1.220
Name of the Road : Mahanada From to Madhubani	
Scheme/Programme : MAINTENANCE	
Package No.:	Road ID No.:
Status of the Project :	Ongoing/Completed/Under Maintenance
Work is a case of :	New Connectivity/Up Gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	15'
b)	Condition of Surfacing	15'
c)	Riding Quality	15'
d)	Road Camber	15'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	-
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :	Satisfactory (S)	15'
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

NAME :

DESIGNATION :

[Signature]
17/12/2020
A.E

(Signature)