

FIELD INSPECTION REPORT

pitipainti

Date of Inspection:	16/12/2020	District:	Bhagalpur
Division:	Kahalgau	Length (km):	1.0 km
Name of the Road:	Naxachak uraon to Pachrukhi		
Scheme/Programme:	MAINTENANCE	GREEN	GTSNY
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Under Maintenance</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/V S
b)	Condition of Surfacing	S/V S
c)	Riding Quality	S/V S
d)	Road Camber	S/V S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
U	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

16/12/2020
(Signature)
At

NAME: