

FIELD INSPECTION REPORT

Date of Inspection :	17-12-2019	District :	Amravati
Division :	11/1/2	Length (km) :	1.10 km
Name of the Road :	M-100, Amravati to Nandgaon via Nandgaon Bypass (Left lane)		
Scheme/Programme :	MAINTENANCE		
Package No. :	Road Id No. :		
Status of the Project :	Ongoing/Completed/Under Maintenance : ☒		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

Sr. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	SU ✓
c)	Riding Quality	SU ✓
d)	Road Curb	- SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f)	Construction joints provided or not (CC Pavement)	- Yes/No
g)	Comparison of Backslope & minimum if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in stone pipe culverts including its painting	SU/SU ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SU/SU ✓
c)	Condition of railings/side approach for Bridges	SU/SU ✓
3.	Road Furniture	
a)	Whether sign boards/informative/stationary Board/ km & 200m marker/Pavement road markings are provided and maintained	- Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	11-ATR

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Ranjit Chaudhary

17-12-2019
(Signature)