

# FIELD INSPECTION REPORT

|                        |                                                            |              |             |
|------------------------|------------------------------------------------------------|--------------|-------------|
| Date of Inspection :   | 16-12-2020                                                 | District:    | Kuthang     |
| Division :             | Kuthang-2                                                  | Length (km): | 0.400 Km    |
| Name of the Road:      | Puccamolma to Mumbur Rd to Andabari Pongbani taluk (UTSNY) |              |             |
| Scheme/Programme:      | MAINTENANCE ✓                                              |              |             |
| Package No.:           |                                                            | Road Id No.: | 21205901895 |
| Status of the Project: | Ongoing/Completed/Under Maintenance ✓                      |              |             |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance ✓               |              |             |

| Sl. No. | Parameters to be checked                                                                                             | Remarks  |
|---------|----------------------------------------------------------------------------------------------------------------------|----------|
| 1.      | <b>Pavement</b>                                                                                                      | S/U — S  |
| a)      | Road Junction condition                                                                                              | S/U — U  |
| b)      | Condition of Surfacing                                                                                               | S/U — U  |
| c)      | Riding Quality                                                                                                       | S/U — S  |
| d)      | Road Camber                                                                                                          | Yes/No ✓ |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓ |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No ✓ |
| g)      | Compaction of flank/slope & raincuts if any                                                                          |          |
| 2.      | <b>Cross Drainage</b>                                                                                                | S/SRI/U  |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U  |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U  |
| c)      | Condition of railings/slab/approach for Bridges                                                                      |          |
| 3.      | <b>Road Furniture</b>                                                                                                | Yes/No ✓ |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |          |
| 4.      | <b>Compliance History</b>                                                                                            | —        |
| a)      | Status of ATR's & any others                                                                                         |          |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | — |
| Satisfactory but requires Improvement (SRI) | — |
| Unsatisfactory (U)                          | U |

*Km*  
16-12-2020  
(Signature)

NAME: