

UTSNY

FIELD INSPECTION REPORT

Date of Inspection :	16/12/20	District:	PATNA
Division :	BARH	Length (km):	0.300
Name of the Road:	Mazatha to Sikandara to Chakalam		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing Completed Under Maintenance		
Work is a case of:	New Connectivity Up gradation Maintenance		UTSNY
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S U	
b)	Condition of Surfacing	✓ S U	
c)	Riding Quality	✓ S U	
d)	Road Camber	S U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes No ✓	
g)	Compaction of flank slope & raincuts if any	Yes No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI U	
b)	Condition of Abutment & Wing walls Slab in RCC culverts	S SRI U	
c)	Condition of railings slab approach for Bridges	S SRI U	
3.	Road Furniture		
a)	Whether sign boards informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	No ATR	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

Bikumar
16/12/20
(Signature)

NAME: BINOD KUMAR
JUNIOR ENGINEER