0

FIELD INSPECTION REPORT

Date of	Inspection : 1	(12 2	I no.	
Division: 16.12.20 Division: 16.12.20 Normality Floring East-1			District: M142-flax/our	
Name of the Road: P.M. b. Sy Sodak +			Length (km): 0.840 Km	
Scheme	Programme:	MAINTENANCE	ow.D.Jalobar Kotaler Ma	of bilanns
Packag		MAINTENANCE	Road Id No.: 31507201	
	of the Project:	Ongoing/Completed	Road Id No.: 31507201 /Under Maintenance	334
	s a case of:	New Connectivity/U	p gradation/ Maintenance	
Sl. No.				Remarks
1.	Pavement			Remarks
a)	Road Junction condition			_S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			and the selection
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			To and part
a)	Status of ATR's & any others			S

Overall Rating

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

16/12/20

(Signature)

NAME: Rakeshkr. Raushan

DESIGNATION: JE