

(13)

FIELD INSPECTION REPORT

| | | |
|------------------------|---|-----------------------|
| Date of Inspection : | 16.12.2020 | District: MUZAFFARPUR |
| Division : | EAST-1 | Length (km): 1.435 km |
| Name of the Road: | Beniyapur kandi me Bhuneshwar Ray ke Ghar se to harijen taluk Nash nadi taluk | |
| Scheme/Programme: | MAINTENANCE | |
| Package No.: | Road Id No.: 31507201348 | |
| Status of the Project: | Ongoing/Completed/Under Maintenance | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | |

| Sl. No. | Parameters to be checked | Remarks |
|---------|--|-----------|
| 1. | Pavement | |
| a) | Road Junction condition | ✓ S/U |
| b) | Condition of Surfacing | ✓ S/U |
| c) | Riding Quality | ✓ S/U |
| d) | Road Camber | ✓ S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓ Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | ✓ Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No ✓ |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U ✓ |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓ |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | |

Overall Rating :

| | |
|---|-------|
| Satisfactory (S) | |
| Satisfactory but requires Improvement (SRI) | 'SRI' |
| Unsatisfactory (U) | |

Portion of BT Surface damaged during flood 2020.

Ashutosh
16.12.2020.

(Signature)

NAME: ASHUTOSH KUMAR

DESIGNATION: DE-SARBA