

FIELD INSPECTION REPORT

Date of Inspection:	15/12/2020	District:	Bhagalpur
Division:	Kahalgaon	Length (km):	1.70 km
Name of the Road:	Nadhi Diyara to PMHSY		
Scheme/Programme:	MAINTENANCE	GTSNY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameter to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/B	S
b)	Condition of Surfacing	S/U	U
c)	Riding Quality	S/B	S
d)	Road Camber	S/B	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of Bank/slope & raincuts if any	Yes/No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NO
4.	Compliance History		
i)	Status of AFR's & any others	200m missing No	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Damaged in 2020 Flood. Part A done and Required part-B.

@
17/12/2020
(Signature)

NAME:

ADDRESS: