

pirpainti

FIELD INSPECTION REPORT

Date of Inspection:	15/12/2020	District:	Bhagalpur
Division:	Kahelgaon	Length (km):	2.0 km
Name of the Road:	Bhuanasi to pmgsy		
Scheme/Programme:	MAINTENANCE		GTSNY
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of:	Now Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/S	S
b)	Condition of Surfacing	S/S	S
c)	Riding Quality	S/S	S
d)	Road Camber	S/S	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	No
2.	Cross Drainages		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
i)	Status of ATR's & any others	No	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 15/12/2020
 (Signature)
 H

NAME: