

# FIELD INSPECTION REPORT

Date of Inspection :	7/12/2020	District:	East Champaran
Division :	Motihari	Length (km):	1.00
Name of the Road:	H/O MDA to H/O Hissatul prasad		
Scheme/Programme:	MAINTENANCE	BITUMY	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		~S/U
b)	Condition of Surfacing		~S/U
c)	Riding Quality		~S/U
d)	Road Camber		~S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		N.A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

*(Signature)*  
8/12/20

NAME: Akhilesh prasad

DESIGNATION: A.E

Name: Ajay Kumar

Design: J.E

*(Signature)*