

FIELD INSPECTION REPORT

Date of Inspection :	7/12/2020	District:	East Champaran
Division :	Mohiwan	Length (km):	1.528
Name of the Road:	pmssy chubhusahy 9 de motximal/pur g hat		
Scheme/Programme:	MAINTENANCE	mmssy	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	~8/U	
a)	Road Junction condition	~S/U	
b)	Condition of Surfacing	~8/U	
c)	Riding Quality	~8/U	
d)	Road Camber	Yes/No	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	~Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	~Yes/No	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage	~S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture	Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	~Yes/No	
4.	Compliance History	N.A	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Akhlesh prasad

DESIGNATION: A E

Name: Ajay Kumar

Design: J.E

7/12/2020
J.E

7/12/20
AE
(Signature)