

FIELD INSPECTION REPORT

Date of Inspection :	7/12/2020	District:	East Champaran
Division :	Motihari	Length (km):	1.223
Name of the Road:	pmgsy chichwaha ya ge. maluh Toli		
Scheme/Programme:	MAINTENANCE	Road Id No.:	MMG15Y
Package No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Finding - 20.0m surface is damaged due to flood 2020 its repair interest in FPR MFS. Rest swt is satisfactory.

08/12/20
(Signature) AE.

NAME: Akhilesh prasad

DESIGNATION: A.E

Name : AJAY KUMAR

Design: J.E

08/12/2020