

FIELD INSPECTION REPORT

Date of Inspection : 17/12/2020		District: Aram'ia
Division : Porbeshganj		Length (km): 0.995 Km
Name of the Road: NH57 to Khom Tola		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Remarks	Remarks
Pavement		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ?
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U } N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
Compliance History		
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRP
Unsatisfactory (U)	

NAME:

Alc
(Signature)
17/12/20
18