FIELD INSPECTION REPORT

Date of Inspection: 16/12/2020			District : Purnea	
Division : Purnea			Length (Km): 0, 450 KM	
Name of	f the Road : N	iusahman tola to L		
Scheme	/Programme :	Maintenance \		
Package No. :		Road ID No. :		
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is	a case of:	New Connectivity/Up gradation/Ma	intenance ~	
Sl. No		Parameters to be Checked		Remarks
1).	Pavement			
a)	Road Junction condition		C8/U	
b)	Condition of Surfacing		L8/U	
c)	Riding Quality			S/U
d)	Road Camber		√8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes(No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of Flank/Slope & Raincuts if any		Yes/No	
2).	Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U	
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U	
3).	Road Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		Yes/No	
4).	Compliance History			
a)	Status of ATR's	& any others	1	
Overall F	Rating :	Satisfactory (S)	·	
, vian i		Satisfactory but requires Improver	ment (SRI)	CPI

Name: Glasendag Ergend Himany.

Unsatisfactory (U)

Degisnation: J'E RWD, Works Division, Purnea. (Signature)