

FIELD INSPECTION REPORT

Date Of Inspection <u>3/12/2020</u>		District <u>Bhojpur</u>
Division <u>Piyo</u>		Length (km): <u>0.550</u>
Name of the Road:	<u>Lo22 to Gosia Tala</u>	
Scheme/Programme	<u>MAINTENANCE M.M.G.S.Y</u>	
Package No.:	Road Id No.: <u>10401801327</u>	
Status of the Project :	<u>Ongoing/Completed/Under Maintenance</u>	
Work is a case of :	<u>New Connectivity/Up gradation/Maintenance</u>	
SI No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	<u>✓S/U</u>
b)	Condition of Surfacing	<u>✓S/U</u>
c)	Riding Quality	<u>✓S/U</u>
d)	Road Camber	<u>✓S/U</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	<u>Yes/No</u>
f)	Contraction Joints provided or not (CC Pavement)	<u>Yes/No</u>
g)	Compaction of flank/slope & raincuts if any	<u>Yes/No</u>
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<u>✓S/SRI/U</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>S/SRI/U</u>
c)	Condition of railings/slab/approach for Bridges	<u>S/SRI/U</u>
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>✓Yes/No</u>
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	<u>1S</u>
Satisfactory but requires Improvement (SRI)	<u>—</u>
Unsatisfactory (U)	<u>—</u>

Name: Kamlesh Kumar

Designation: J-E 3/12/2020

K.K.
3/12/2020
(Signature)