## FIELD INSPECTION REPORT

			District: Madhubani		
Date of Inspection: 16-12-2020				310011101001	
Divisio	1910n:				
		Maintenance	to Yaday tol.		
	/Programme:	MAINTENANCE	Road Id No.:		
Packago	e No.:	Ongoing/Complet	ed/Under Maintenance		
Status o	f the Project:	New Connectivity	/Up gradation/ Maintenance		
Work is a case of: Sl. No.		Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
	Condition of Surfacing			✓S/U	
<u>b)</u>				_/S/U	
c)	Riding Quality			√S/U	
d)				Yes/No	
e)	aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/slope & raincuts if any  Yes/No				
2.	Cross Draina		A CONTRACTOR OF THE PARTY OF TH	Marie Control of the Control	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR's & any others				

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: CHITRANSAN RAHUL

DESIGNATION: JE