## FIELD INSPECTION REPORT

Date of Inspection: 16/12/2020 District: Wainth					1	
Division: Mahauta			Length (km): 1.525UM			
Name o	f the Road: AV	chini Madh A	lishedh cheek pos	+ +	s Akhini	Middle school.
	/Programme:	MAINTENANCE		MAMARD		
Package No.:			Road Id No.:			
	of the Project:	The second secon	I/Under Maintenance	ataminahan meneranjan meneran		
Work is	s a case of:	New Connectivity/U	Jp gradation/ Maintenance			
Sl. No. Parameters to			be checked		Remarks	
1.	Pavement			1 2 (2-della)	Andrew Control	
a)	Road Junction condition				<b>~</b> \$/U	and a
b)	Condition of Surfacing				∕S/U	
e)	Riding Quality				<b>∕</b> \$//U	
d)	Road Camber				∕S/U	
e)	Whether free from defects such as visible cracks, expos aggregates in case of CC Pavement.				Yes/No	
f)	Contraction Joints provided or not (CC Pavement)				Xes/No	
g)	Compaction of flank/slope & raincuts if any				Xes/No	
2.	Cross Drainage				A P	3 d
a)	Condition of head walls in Hume pipe culverts including its painting				∕\$/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges				8/SRI/U	
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained			200m	Yes/No	No
4.	Compliance I	History	5 5212			
a)	Status of ATR's & any others				No	30 mm 27
Overall	Rating :					
	-	Satisfactory (S)		NE DA VIII		
A STATE OF THE PARTY OF THE PAR			requires Improvement (\$	SRI) LRI		
		Unsatisfactory (U	.)		*	
Information Board maintained.			R.F not			

NAME: Md. Janil Abul Hossau