

FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020	District: Rohas
Division : R.W.D - Bikaner	Length (km): 1.4/3 km
Name of the Road: TD1 (NH-30) to Mahorah	
Scheme/Programme: MAINTENANCE	187 year maintenance (P.M.G.S.Y)
Package No.: BR-28R-019	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.O

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Satish Kumar

16/12/2020
(Signature)
J.E.