FIELD INSPECTION REPORT

Date of Inspection:- 17-12-20 D			District:- Sheohar.	District:- Sheohar.	
Division:-RWD, Works Div. Sheohar Length (km):- 113 Name of the Road:- how com Pambour Show Ke Sonwye to Re			7 RM		
Name	of the Road:- le	emous Rous land a S	iron Kertanwaya to Ka	www.sohoo	
	errogramme:-	MAINTENA	INCE NOB Brie	WS	
	ge No.:-		Road Id No.:		
Mante	tatus of the Project: Ongoing/Completed/Under Maintenan Vork is a case of: New Connectivity/Un gradation/ Maintenan			e	
SI. No.		New Connectivity	/Up gradation/ Mainte	enance	
-	Parameters to be checked		Remarks		
1.	Pavement				
a)	Road Junction condition			∿S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage			- I carrio	
a)	Condition of head walls in Hume pipe culverts including its painting			~S/SRI/U	
b)	Condition of Abutments & Wing walls, Slab in RCC culverts			·S/SRI/U	
c)	Condition of railing/slab/approach for bridges			'S/SRI/U	
3.	Road Furniture				
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained			~Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others			ND	

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Pam Biron Sirgh

(Signature)

DESIGNATION:- A.E.