FIELD, INSPECTION REPORT

		=	KEI OKI
in the same of	Date of Inspection:	1/2/2020	District: JEHANABAD
Division: Temporabag			Length (km): 1.750 Km
N	ame of the Road: 70	2 to Chhajjopus	1 /30 /2"
Scheme/Programme: PM 43 Y			MAINTENANCE
Package No: 198-1973			Road Id No.:
Sta	atus of the Project:	Ongoing/Completed/Under grad	ation/Maintenance
Wo	ork is a case of:	New Connectivity/Up gradation/	Maintenance
S.N	Parame	ters to be cheeked	Remarks
1.	Payment		
a)	Road Junction condition	J8/U	
b)	Condition of Surfacing		8/U
c)	Riding Quality		S/U
d)	Road Camber		SU
e)	Whether free from defects such as visible cracks, exposed		
	aggregates in case of CC		103110
f)	Contraction joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slop		Yes/No
SA.	Cross Drainage		
-		n Hume pipe culverts including	s/sri/U
	its painting	p.pe carrens menading	Jordan C
	Condition of Abutment culverts.	& Wing walls, Slab in RCC	S/SRI/U N/A
) (Condition of railings/slab/a	approach for Bridges	S/SRI/U N/A
remarket annual	toad Furniture		
W	hether sign boards/inform	natory/cautionary Board/km &	Yes/No
ž.	00m stones/Pavement roa aintained	ad markings are provided and	
Co	ompliance History	ranger in a larger	
-	itus of ATR's & any other	NO	

Overall Rating:

1

Satisfactory (S)	ς
Satisfactory but requires	
Improvement (SRI)	_
Unsatisfactory (U)	_

Poamit Kr.
17/12/2020

Signature

NAME: PRANTT KVMAR DESIGNATION: JE