## FIELD INSPECTION REPORT

Date of Inspection: 16.12, 2020			District: East chambaran	
Division: Areral				
lame of	f the Road: M	MAINTENANCE	Ki Tolo to To	7 7 8 80
		MAINTENANCE		***
ackage			Road Id No.: 31708301266	
Status of the Project: Ongoing/Complet Work is a case of: New Connectivity			onder wantiellance	1,000
Section start	0.000	New Connectivity	Up gradation/ Maintenance	
Sl. No.	The Little Courses Children	Parameters (	o be checked	Remarks
1.	Pavement			
a)	Road Junction	S/J		
b)	Condition of S	S/V		
c)	Riding Quality			S/J2
d)	Road Camber			S/U/
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
p) .	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniti	ire		44457 TES
a)	Mounteene Board Not a Kally			Yés/No
4.	Comphance	IISTOLY		
a)	Status of ATR	's & any others	3 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	No.

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	CRT
Unsatisfactory (U)	3/4

(Signature)

NAME: He dre Soh

DESIGNATION: AE RWP.

Acerg

Scanned with CamScanner