

# FIELD INSPECTION REPORT

|                                   |                                                                                                                      |                                                     |
|-----------------------------------|----------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|
| Date of Inspection : 13.12.20     |                                                                                                                      | District: Murugur Taluk                             |
| Division : P.W.D. Murugur - West  |                                                                                                                      | Length (km):                                        |
| Name of the Road: M.C. S. Y. Road |                                                                                                                      | Scheme/Programme: MURUGUR TO SATHANUR TALUK MURUGUR |
| Package No.: MAINTENANCE          |                                                                                                                      | Read Id No.: 7/58740/221                            |
| Status of the Project:            |                                                                                                                      | Ongoing/Completed/Under Maintenance                 |
| Work is a case of:                |                                                                                                                      | New Connectivity/Up gradation/ Maintenance          |
| Sl. No.                           | Parameters to be checked                                                                                             |                                                     |
| 1.                                | Pavement                                                                                                             | Remarks                                             |
| a)                                | Road Junction condition                                                                                              | ✓ S/U                                               |
| b)                                | Condition of Surfacing                                                                                               | ✓ S/U                                               |
| c)                                | Riding Quality                                                                                                       | ✓ S/U                                               |
| d)                                | Road Camber                                                                                                          | ✓ S/U                                               |
| e)                                | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No                                            |
| f)                                | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No                                            |
| g)                                | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No                                            |
| 2.                                | Cross Drainage                                                                                                       |                                                     |
| a)                                | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U                                           |
| b)                                | Condition of Abutment & Wing walls. Slab in RCC culverts                                                             | ✓ S/SRI/U                                           |
| c)                                | Condition of railings/slab/approach for Bridges                                                                      | ✓ S/SRI/U                                           |
| 3.                                | Road Furniture                                                                                                       |                                                     |
| a)                                | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No                                            |
| 4.                                | Compliance History                                                                                                   |                                                     |
| a)                                | Status of ATR's & any others                                                                                         | N/A                                                 |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

13.12.20  
(Signature) J2

NAME: Satya Narayan Prasad

DESIGNATION: J.E. P.W.D.