

# FIELD INSPECTION REPORT

DATE OF INSPECTION:	09.12.2020 DISTRICT:-PURNEA	
DIVISION:	DHAMDHAHA, LENGTH: 1.025 KM	
NAME OF THE ROAD:	Tol to Kori Bin Tola	
SCHEME/PROGRAMME:	NABARD MAINTENANCE	
PACKAGE No:	ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SLNO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	'S'
B	CONDITION FO SURFACING	'S'
C	RIDING QUALITY	'S'
D	ROAD CAMBER	'S'
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	'S'
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	'S'
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	'SRI'
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	'S'
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'SRI'
4	COMPLIANCE HISTORY	
A	STATUS OF ATR"s & ANY OTHERS	N.A
OVERALL RATING		
	SATISFACTORY(S)	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	'SRI'
	UNSATISFACTORY(U)	

NAME: Surendra prasad Singh  
DESIGNATION: Junior Engineer

S. Singh  
SIGNATURE  
10/12/2020

Scanned by CamScanner

Scanned by CamScanner