

FIELD INSPECTION REPORT

Date of Inspection :	16.12.2020	District:	GAYA
Division :	SHERGHATI	Length (km):	1.238 km
Name of the Road:	LO27 TO TETARIYA KALAN		
Scheme/Programme:	MAINTENANCE	PMGSY	
Package No.:	BR-12R-996	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	/

NAME: Dr. Raj Kishore Prasad

DESIGNATION: Assistant Engineer / Dohri

[Signature]
16.12.20
(Signature)