

FIELD INSPECTION REPORT

Date Of Inspection <u>3/12/2020</u>		District <u>Bhojpur</u>
Division <u>Piro</u>		Length (km): <u>1.10 km</u>
Name of the Road:	<u>2023 TO Bichhiao Shiv Mandir Tala</u>	
Scheme/Programme	<u>MAINTENANCE M.M.G.sy</u>	
Package No.:	Road Id No.: <u>10401812026</u>	
Status of the Project :	<u>Ongoing/Completed/Under Maintenance</u>	
Work is a case of :	<u>New Connectivity/Up gradation/Maintenance</u>	
SI No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	<u>✓</u> S/U
b)	Condition of Surfacing	<u>✓</u> S/U
c)	Riding Quality	<u>✓</u> S/U
d)	Road Camber	<u>✓</u> S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	<u>✓</u> Yes/No
f)	Contraction Joints provided or not (CC Pavement)	<u>✓</u> Yes/No
g)	Compaction of flank/slope & raincuts if any	<u>✓</u> Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<u>✓</u> S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<u>Not exist</u> S/SRI/U
c)	Condition of railings/slab/approach for Bridges	<u>Not exist</u> S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<u>✓</u> Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

1

Satisfactory (S)	<u>157</u>
Satisfactory but requires Improvement (SRI)	<u>—</u>
Unsatisfactory (U)	<u>—</u>

Name:

Kamlesh Kumar

Designation

J.E.

K.P.
3/12/2020
(Signature)