

FIELD INSPECTION REPORT

Date Of Inspection 3/12/2020		District Bhojpur
Division Piro		Length (km): 2.50
Name of the Road:	TOI TO Khandoul	
Scheme/Programme	MAINTENANCE M.M.G.S.Y	
Package No.:	Road Id No.: 10401813003	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New, Connectivity/Up gradation/Maintenance	
SI No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & rainouts if any	✓ Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	Not exist S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

1

Satisfactory (S)	1 S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Name:

Kamlesh Kumar

Designation

J.E.

K. Kumar
3/12/2020
(Signature)