


# FIELD INSPECTION REPORT

|                                 |                                                                                                                      |                                           |          |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------|----------|
| Date of Inspection : 16.12.2020 |                                                                                                                      | District : GAYA                           |          |
| Division : Neemchak Bathani     |                                                                                                                      | Length (Km.) : 1.356 km                   |          |
| Scheme/Programme:               |                                                                                                                      | MAINTENANCE To 8 to Dohari                |          |
| Package No. : BR-612R-562       |                                                                                                                      | Road Id No. :                             |          |
| Status of the Project :         |                                                                                                                      | Ongoing/Completed/Under Maintenance       |          |
| Work is a case of :             |                                                                                                                      | New Connectivity/Up gradation/Maintenance |          |
| Sl. No.                         | Parameters to be checked                                                                                             |                                           | Remarks  |
| 1                               | <b>Pavement</b>                                                                                                      |                                           |          |
| a)                              | Road Junction condition                                                                                              |                                           | S/U      |
| b)                              | Condition of Surfacing                                                                                               |                                           | S/U      |
| c)                              | Riding Quality                                                                                                       |                                           | S/U      |
| d)                              | Road Camber                                                                                                          |                                           | ✓ S/U    |
| e)                              | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | NA                                        | Yes/No   |
| f)                              | Contraction Joints provided or not (CC Pavement)                                                                     | NA                                        | Yes/No   |
| g)                              | Compaction of flank/slope & raincuts if any                                                                          | ✓                                         | Yes/No   |
| 2                               | <b>Cross Drainage</b>                                                                                                |                                           |          |
| a)                              | Condition of head walls in Hume pipe culverts including its painting                                                 |                                           | S/SRI/U  |
| b)                              | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             |                                           | S/SRI/U  |
| c)                              | Condition of railings/slab/approach for Bridges                                                                      | ✓                                         | S/SRI/U  |
| 3                               | <b>Road Furniture</b>                                                                                                |                                           |          |
| a)                              | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |                                           | Yes/No ✓ |
| 4                               | <b>Compliance History</b>                                                                                            |                                           |          |
| a)                              | Status of ATR's & any others.                                                                                        |                                           |          |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | —   |
| Satisfactory but requires improvement (SRI) | SRI |
| Unsatisfactory (U)                          | —   |

  
 16.8.2020  
 J.E