


# FIELD INSPECTION REPORT

Date of Inspection : 7.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 2.489	
Name of the Road : PMGSY Kasimpur (Fazilpur) to Grotiya village via paswan tola bajeantwahi stan			
Scheme / Programme : MMGSY (MCH)		Road Id No : 20703212014	
Package No :		Road Id No : 20703212014	
Status of the Project :		Ongoing / Completed / Under Maintenance ✓	
Work is a case of :		New Connectivity / Up gradation / Maintenance	
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No ✓	
g)	Cmpaction of flank/slope & raincuts if any	Yes / No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	] N/A
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating			
	Satisfactory (S)	1	
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (II)	1	

Note: Logo board not paint & maintain  
BT crust damage, pot hole in some part

NAME: Rajeshwar Rajak  
DESIGNATION: A.E

  
17.12.2020  
Signature