


FIELD INSPECTION REPORT

Date of Inspection : 16.12.2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 1.228 Km.	
Name of the Road : Fulwari Simaria Mohammadpur more to Mohammadpur.			
Scheme / Programme : MMGSY (SC)			
Package No. :		Road Id No. : 20703213005	
Status of the Project : ☒ Ongoing / ☐ Completed / ☐ Under Maintenance			
Work is a case of : ☒ New Connectivity / ☐ Up gradation / ☐ Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	U
b)	Condition of Surfacing	S/U	U
c)	Riding Quality	S/U	U
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	NO
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes / No	NO
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	} S
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NO
4.	Compliance History		
a)	Status of ATR's & any others		
Overall Rating :			
	Satisfactory (S)	—	
	Satisfactory but requires Improvement (SRI)	—	
	Unsatisfactory (U)	U	

Note: Jungle cleaning & flanks are not maintained. Riding quality is very poor.

NAME : Rakesh Raman Singh
DESIGNATION : Assistant Engineer.


16/12/20
Signature RB