

# FIELD INSPECTION REPORT

Date of Inspection :		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 0.59	
Name of the Road :		PMUSY Halkasachak (Bajrangwale Mandar)	
Scheme / Programme :		to Karyanand Roy House	
Package No. :		MMUSY (SC)	
Status of the Project :		Road Id No. : 20703213020	
Work is a case of :		Ongoing / <input checked="" type="checkbox"/> Completed / Under Maintenance	
Work is a case of :		New Connectivity / Up gradation / <input checked="" type="checkbox"/> Maintenance	
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	S
b)	Condition of Surfacing	S / U	S
c)	Riding Quality	S / U	S
d)	Road Camber	S / U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	Yes
g)	Cmpaction of flank/slope & raincuts if any	Yes / No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	-
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	-
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	-
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NO
4.	Compliance History		
a)	Status of ATR's & any others		
Overall Rating			
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	SRI	
	Unsatisfactory (U)		

Note: ① NO maintenance board ② Main board painting to be done  
③ 200m post to be fixed

NAME: Hridya Mondal

DESIGNATION: E.E

Signature

16/12/2020