


FIELD INSPECTION REPORT		
Date of Inspection :	17.12.2020	District : Bhagalpur
Division :	Nawgachhiya	Length (km) : 1.50 km
Name of the Road :	L029 - NH 31 to murli channahar	
Scheme/Programme :	Maintenance PMUSY I	
Package No. :	BR 06R 288	Road Id No. :
Status of the Project :	Ongoing/Completed/Under Maintenance	PMUSY I
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing At some points surface reqd. maint.	S/U ✓
c)	Road Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culvert including its painting.	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3	Cross Drainage	
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	✓ Yes/No
4	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	

NAME :

DESIGNATION :

- Ramashisha Prasad
E.E., RWD (WD) Nawgachhiya
- Himanshu Shenhaz Prasad
A.E., Rangra Chowk


 कार्यपालक अभियन्ता
 (Signature)
 ग्रामीण कार्य विभाग
 कार्य प्रमण्डल नवगछिया
 17.12.2020
 AE