

FIELD INSPECTION REPORT

Date of Inspection : 17/12/20		District: Sahansu
Division : Simra Bahadurgarh		Length (km): 1.911 km
Name of the Road: Jamunia to Pipra Mushahari		
Scheme/Programme: MAINTENANCE		Road Id No.:
Package No.:		Status of the Project: ☒ Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ ☒ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

N.A.

Work
Started


Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N.A.

NAME: ASHOK KUMAR

DESIGNATION: Executive Engineer


 17/12/20
 (Signature)