

1      2

**FIELD INSPECTION REPORT**

Date of Inspection : 17/12/20		District: Saharwa
Division : Saharwa Simr Bakhtiyapur		Length (km): 0.493 K.m
Name of the Road: MDR TO 1 to Teghra		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

N. A.  
Work not yet started

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

N. A.

Ashu  
17/12/20  
(Signature)

NAME: ASHOK KUMAR

DESIGNATION: Executive Engineer