## FIELD INSPECTION REPORT

_			THE PORT		
	Date of Inspection: 16/12/2020 District: O. ho				
Division: Sv		Snoanl	Length (km): 4.85 km		
	ame of the Road:	katayiya to Di	udha Keotna Rand	and the company of the contract of the contrac	
Sc	Package No.: Road Id No.: 2100490 Status of the Project: Ongoing/Completed/Under Maintenance				
Pa					
Wo					
	New Connectivity/Up gradation/ Maintenance				
51.	No.	o. Parameters to be checked			
1	. Pavement	Pavement			
a	a) Road Junction condition				
b)		tion of Surfacing		S/U	
c)				S/U S/U	
d)	Road Camber				
- 1				S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No-		
f)	Contraction Joints provided or not (CC Pavement)		A STATE OF STREET OF STREET, S		
		flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			1 CS/IVO	
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U		
)	Condition of Ab	dition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
)		Condition of railings/slab/approach for Bridges			
, 1	Road Furniture		S/SRI/L		
	N/A			March on \$55 March on Science and District of the Science and Control of th	
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No		
	Compliance History				
	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

pt at very den en-lebentuto repaised:

NAME: SANGEY KUMAR

DESIGNATION: EXECUTIVE ENGINEER\_ CE-30HF, RWD, Patra