FIELD INSPECTION REPORT

		FIELD INSPEC	<u>TION REPORT</u>		
Date of Inspec	tion: 16	6.12.2020	District: Araria		
Division: Forher on in the day 7.50 KI					
Name of the Road: Bickooky at Dane			madighi Nepal Bow	eden	
Scheme/Progr	amme:	MAINTENANCE	TANKE ()		
Package No.:			Rond Id No.:		
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance Remarks			
Sl. No.		Parameters to l	o checked	Kejmarks	
1. Pave	ment	WALL		√S/U	
a) Road	Road Junction condition				
b) Cond	Condition of Surfacing				
c) Ridin	Riding Quality				
d) Road	Road Camber				
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f) Contra	Contraction Joints provided or not (CC Pavement)				
g) Comp	Compaction of flank/slope & raincuts if any				
2., Cross	Drainage		A CONTRACTOR	新走運行	
	Condition of head walls in Hume pipe culverts including its painting				
	Condition of Abutment & Wing walls, Slab in RCC culverts				
c) Condit	Condition of railings/słab/approach for Bridges				
3. Road I	Furniture		Market de la	,上《春溪	
a) Whether stones/l	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4. Compli	iance His	lory 1	特别是中国中国共享省	が記れる。	
a) Status o	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	•

(Signature)

NAME: CHANDRA SHEKHAR ALAD

EXECUTIVE ENGINEER