## FIELD INSPECTION REPORT

Data of In	spection:	1/12/2020	District: Vai Shali		
			Length (km): 3.00 km		
	the Road:	NH-103 GU-	ru chowk Se Kaj	ri Burju	
	rogramme:	MAINTENANCE	J		
Package l			Road Id No.:		
Status of the Project: Ong		Ongoing/Completed	ngoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.	by the state	Parameters to	be checked	Remarks	
7,	Pavement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			. S/U _/	
c)	Riding Quality			~\$/U	
d)	Road Camber			_8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4,	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	~
Satisfactory but requires Improvement (SRI)	5e I
Unsatisfactory (U)	-

Work in flank started

(Signature)

NAME: RATUITH SINGH

DESIGNATION: