

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020 District: West Champaran
 Division: RWD Works Division Bettiah Length (km): 3.74 Km
 Name of the Road: Bakuchiya to Laxmipuri
 Scheme Programme: MAINTENANCE

Package No.: 19-20/12 Road Id No: 3180 3801012
 Status of the Project: Ongoing Completed Under Maintenance

Work is a case of: New Connectivity Upgradation Maintenance New Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	ST
b)	Condition of Surfacing	ST
c)	Riding Quality	ST
d)	Road Camber	ST
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & ramps if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Frame pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings side approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards informative cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NA
 work has not started

(Signature)

NAME: Ratnesh Paswan

DESIGNATION: — Executive Engineer

21/12/2020
 17-12-2020