

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020 District: West Champaran
 Division : - R.W. D work in Bagaha Length (km): 2.185
 Name of the Road: G. M. Bhulbariga Se Bheri Haritola to Bheri
 Scheme/Programme: MAINTENANCE marakiyama p.m.s.s.y sarok-jak
 Package No.: RM/NE/BAG / 20/002 Road Id No.: 31809101006
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance - New Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S U
b)	Condition of Surfacing	S U
c)	Riding Quality	S U
d)	Road Camber	S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raneuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

H-A.
 work has not started
 notice issue

NAME: Ratnesh Paswan
 DESIGNATION: Executive Engineer

(Signature)

20/12/2020
 17.12.2020

Work has not started